

Arlene
Make sure this completion
yets inte CERCLIS.

U.S. ENVIRONMENTAL PROTECTION AGENCY POLLUTION REPORT

FINAL POLREP

DATE: 6/9/94

FROM: BRAD BENNING/SAM BORRIES, OSC, EERB, RESPONSE SECTION #2, U.S. EPA

TO: R. KARL, BRANCH CHIEF, EERB, US EPA, CHICAGO, IL...(VIA FAX)
D. BRUCE, SECT. CHIEF, EERB, US EPA, CHICAGO, IL...(VIA FAX)
S. PROUT, OFF. REG. COUNSEL, US EPA, CHICAGO, IL...(VIA FAX)
J. CISNEROS, ESS, US EPA, CHICAGO, IL....(VIA FAX)
T. LESSER, OPA, US EPA, CHICAGO, IL....(VIA FAX)
T. JOHNSON, US EPA, OSWER, WASHINGTON D.C...(VIA FAX)
U.S. COAST GUARD, DISTRICT 9.....(VIA FAX)
U.S. FISH AND WILDLIFE SERVICE, IL....(VIA FAX)
R. O'HARA, IEPA....(VIA FAX)

SUBJECT: LANSON CHEMICAL SITE, EAST ST. LOUIS, IL

POLREP: POLREP 28

SITE NO: RK

D.O. NO: 7460-05-230

RESPONSE AUTHORITY: CERCLA NPL STATUS: NOT ON THE NPL STATE NOTIFICATION: IEPA

STATUS OF ACTION MEMORANDUM: SIGNED ON 06-18-92; \$2 MILLION AND

12 MONTH EXEMPTION SIGNED ON 7/16/93

START DATE: 6/1/92

1. SITUATION: 5/24/94 - 5/26/94

The Lanson Chemical site is located at 31st Street and Piggott Street in East St. Louis, St. Clair County, IL. The 5-acre site consists of a main building containing several process storage tanks, an outside bermed area containing process storage tanks, and a storage shed. The site assessment identified 45 process storage tanks, 46 drums, and other containers on-site containing solvents, oils, and resins. Approximately half of the 100,000 gallons of waste is contaminated with Polychlorinated Biphenyls (PCBs).

2. ACTIONS TAKEN

WEATHER: PARTLY CLOUDY SKIES, WARM, TEMPERATURES 75 - 80 °F.

On 5/24/94, after verifying cleanup levels had been achieved in all 4 excavation areas, via confirmation sample analysis, the U.S. EPA remobilized the ERCS and TAT contractors on-site to load

PCB-contaminated soil that had been excavated and stockpiled. A total of 13 loads of soil, approximately 234,000 kilograms (kgs) in weight, were transported off-site for final disposal at the Chemical Waste Management (CWM) facility located in Emelle, Alabama. A delay in loading trucks occurred while a service truck was called out to repair a flat tire to the rubber tired loader.

On 5/25/94, ERCS and TAT continued loading contaminated soil onto transport trucks, loading 9 trucks with an estimated weight of 162,000 kgs, for transportation and off-site disposal at the CWM facility in Emelle, Alabama. The crew used clean topsoil to backfill the former tank area (Area T).

On 5/26/94, a total of 16 loads of contaminated soil, approximately 288,000 kgs, were loaded, transported, and disposed of at the CWM facility. All crushed, empty drums, PPE, and other debris was also loaded and disposed of with the contaminated soil. Received two loads of gravel used to fill in around Area B near the loading dock. The crew finished backfilling, reseeding and fertilizing excavated areas. All personnel were demobed, and all equipment was demobed the following day.

3. FUTURE ACTIVITIES

5/27/94 -> (ompletion 1) ate

None anticipated.

4. COSTS (estimated as of 5/28/94)

	ERCS (IT CORP)	ERCS (RIEDEL)	TAT (E & E)	
AMOUNT BUDGETED	\$1,500,000.00 \$1,437,721.00	\$810,000.00 \$610,000.00	\$118,000.00 \$111,285.59	
AMOUNT REMAINING	\$ 62.279.00	\$190,000.00	\$ 6,714.41	

WASTE DISPOSAL TABLE LANSON CHEMICAL SITE

	T			
WASTE DESCRIPTION	DATE SHIPPED	QUANTITY	MANIFEST #	FACILITY
Asbestos	08-11-92	194 bags 31 bundles	FCA # 1766	Hillsboro Litchfield Landfill, Litchfield, IL
Flammable Liquid	09-01-92	5,100 gal.	IL3369058	Clark Processing, Dayton, OH (fuels blending)
Flammable Liquid	09-03-92	5,200 gal.	IL4588352	Clark Processing, Dayton, OH (fuels blending)
Flammable Liquid	09-10-92	5,250 gal.	IL3504150	Clark Processing, Dayton, OH (fuels blending)
Flammable Liquid	09-14-92	5,000 gal.	IL3504151	Clark Processing, Dayton, OH (fuels blending)
Flammable Liquid	09-21-92	71 drums	IL3366997	Clark Processing, Dayton, OH (fuels blending)
PCB Liquids	12-07-92	4,000 gal	IL3425225	Aptus, Aragonite, UT (incineration)
PCB Liquids	12-07-92	5,000 gal	IL3425226	Aptus, Aragonite, UT (incineration)
PCB Soil/Debris	12-09-92	360 tons (15 truck loads)	CWMA6952: 30,31,32, 34-44,47	Chemical Waste Management Inc., Emelle, Alabama (landfill)
PCB Soil/Debris	12-10-92	256 tons (11 truck loads)	CWMA6953: 8-54,21, 17,19,45	Chemical Waste Management Inc., Emelle, Alabama (landfill)
PCB Soil/Debris	12-14-92	12.8 tons (2 truck loads)	CWMA695223, CWMA695224	Chemical Waste Management Inc., Emelle, Alabama (landfill)
PCB Liquids	12-15-92	4,100 gal	IL3425228	Aptus, Aragonite, UT (incineration)
PCB Soil/Debris	12-16-92	5.2 tons	CWMA695225	Chemical Waste Management Inc., Emelle, Alabama (landfill)
PCB Liquids	10-27-93	4,840 gal	MN147168	Aptus, Lakeville, MN (incineration)
PCB Liquids	11-03-93	4,620 gal	IL3425274	Aptus, Coffeeville, KS (incineration)
PCB Liquids	10-27-93	4,840 gal	MN147167	Aptus, Lakeville, MN (incineration)

WASTE DESCRIPTION	DATE SHIPPED	QUANTITY	MANIFEST #	FACILITY
PCB Soil/Debris	05-24-94	234,000 kg	CWMA6846: 68-72, 74- 77, 79-82	Chemical Waste Management Inc., Emelle, Alabama (landfill)
PCB Soil/Debris	05-25-94	162,000 kg	CWMA6846: 83-87, 89- 90, 93-94	Chemical Waste Management Inc., Emelle, Alabama (landfill)
PCB Soil/Debris)	05-26-94	288,000 kg	CWMA684: 695-700, CWMA6992: 01-03,05-09,11-12	Chemical Waste Management Inc., Emelle, Alabama (landfill)

•